


Optical Clear Adhesive Tapes: DuploCOLL[®] OC



Displays with or without touch sensors are bonded securely and without air bubbles directly to the full surface of the front panel using our highly transparent transfer adhesive tapes. This enables unrestricted functionality of all display units as well as the touch sensors. Air bubbles can be removed subsequently with the help of an autoclave.

Features

- Highly transparent
- Acid-free
- Suitable for polycarbonate and PMMA
- Suitable for die-cutting

Products

- DuploCOLL[®] OC Range